


Survey of Section 31 T. 7 R. 26



FIELD NOTES.

Witness Trees	Inches in Diameter	Bearings	Distances in Links	Witness Trees	Inches in Diameter	Bearings	Distances in Links
u	1/2 distance bet N.E. cor. & E. mpt.						
7	Beech 11	N 71½° W	31½				
	Oak 12	S 10° W	29½				
		28 1/2 mpt on solid ledge of stone					
7	oak 13	N 82½° W	4½				
	Oak 6	N 70° W	18				
	Oak 3	S 82° E	22				
		1/2 distance bet S.E. cor. & E. mpt					
8	Hickory 8	N 76° E	14				
	Oak 14	S 76° W	13				
		section corner of section 31, T 82					
7	Larch 3	S 46½° E	23				
	Oak 12	N 79° W	36				
		center of the S.E. quarter					
10	Hickory 14	N 77° E	21				
	Oak 24	S 18° E	28				
		1/2 distance between E. mpt & center					
11	H. yeamore 10	S 40° W	43				
	H. yeamore 2	N 11½° W	13				
		center of the N.E. quarter					
12	H. yeamore 20	S 43° E	51				
	Walnut 13	N 70° W	39				

Survey of Section 32 T. 7 R. 2 E



FIELD NOTES.

Witness Trees	Inches in Diameter	Bearings	Distances in Links	Witness Trees	Inches in Diameter	Bearings	Distances in Links
A 2							
1/2 distance between N.W. corner & N.E. m.p.							
20. Oak 12 N 47° W 44 1/2							
28. Ash 12 N 86° E 64 1/2							
15 1/2 m.p. perpendicular							
2. Oak 12 N 22° W 11							
2. Oak 2 S 66 1/2° W 17							
1/2 distance bet. N. 1/2 m.p. & center							
Walnut 4 S 31 1/2° W 8							
Walnut 3 N 68 1/2° W 28							
36 rods east of the N.W. corner							
B. Walnut 24 S 86 1/2° E 178							
16 rods southwardly from the N.W. corner							
2. Camphor 24 S 77 1/2° E 79 1/2							
16 rods southwardly from a point 4 rods S of a							
point 86 rods east of the N.W. corner							
2. Camphor 6 S 22° W 28							
2. Elm 2 N 1° W 27							